

# POLICY BULLETIN

Tecumseh Compressor Company  
Compressor Group



*Tecumseh*

---

**SUBJECT: Electrical Contactor Specifications**

PB-103

PAGE: 1 of 1

ISSUED: November 27, 1963

REV. DATE: 4/20/2007

Inadequate and/or improperly rated electric contactors are frequently the direct cause of hermetic compressor failure.

In order to establish proper and acceptable standards for contactors approved for use with Tecumseh hermetic compressors. Contactors must qualify per Tecumseh Compressor Company Spec. [H-76](#).

The Tecumseh Compressor Specification [H-76](#) clearly stipulates the test required for approval.

Tecumseh Compressor Company reserves the right to void its hermetic compressor warranty if contractors used are not capable of passing the tests and stipulations included in Specification [H-76](#).